HAER CAL 24-HOPT.V,

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

Merced Irrigation District,
Edendale Creek Turnout and Weir
Hopeton vicinity
Merced County
California

HAER No. CA-192-A

David G. De Vries, photographer

October 1997

CA-192-A-1	WEIR, LOOKING EAST. TURNOUT STRUCTURE IN BACKGROUND.
CA-192-A-2	WEIR, WITH CONCRETE SHEET ON SOUTH BANK AND STILLING WELL ON NORTH BANK.
CA-192-A-3	TURNOUT STRUCTURE, LOOKING EAST, FROM SOUTH SIDE OF CREEK.
CA-192-A-4	ROADWAY AND ACTIVATORS; VIEW TO NORTH.
CA-192-A-5	DETAIL, ACTIVATORS, LOOKING NORTH.
CA-192-A-6	EAST SIDE OF TURNOUT STRUCTURE, LOOKING NORTHWEST. EDENDALE MAIN CANAL IN FOREGROUND.
CA-192-A-7	EAST SIDE OF TURNOUT STRUCTURE, LOOKING WEST AND DIRECTLY ACROSS CANAL.
CA-192-A-8	LOOING WEST DOWN EDENDALE CREEK, FROM ROADWAY CONSTRUCTED OVER TURNOUT STRUCTURE.
CA-192-A-9	LOOKING EAST AT FALLEN CABLE ANCHOR ON NORTH BANK. TURNOUT STRUCTURE AND WEIR IN BACKGROUND.
CA-192-A-10	WOODEN CABLE ANCHOR, ALSO SHOWING ERODED NORTH BANK BELOW WEIR.